



Survey of Section 31 T. 7 R. 2 E



FIELD NOTES.

	Witness Trees	Inches in Diameter	Bearings	Distances in Links	Witness Trees	Inches in Diameter	Bearings	Distances in Links
A ²⁰	$\frac{1}{2}$ distance bet. N.E. cor. & E $\frac{1}{2}$ mpt.							
	Beech	11	N 11 $\frac{1}{2}$ ° W	31 $\frac{1}{2}$				
B	W oak	12	S 10° W	29 $\frac{1}{2}$				
	east $\frac{1}{2}$ mpt. on solid ledge of stone							
C	Hickory	4	N 32 $\frac{1}{2}$ ° W	4 $\frac{1}{2}$				
7	W oak	6	N 70° W	18				
D	Oak	3	S 32° E	22				
	$\frac{1}{2}$ distance bet. S.E. cor. & E $\frac{1}{2}$ mpt.							
E	Hickory	8	N 76° E	14				
	Hickory	14	S 46° W	13				
F	section corner of section 31, T 82,							
9	Gum	3	S 46 $\frac{1}{2}$ ° E	23				
G	W oak	12	N 79° W	36				
	center of the S.E. quarter							
H	Hickory	14	N 77° E	4				
	W oak	24	S 18° E	28				
	$\frac{1}{2}$ distance between E $\frac{1}{2}$ mpt. center							
11	Hyemore	10	S 40° W	43				
	Hyemore	2	N 11 $\frac{1}{2}$ ° W	13				
	center of the N.E. quarter							
12	Hyemore	20	S 43° E	51				
	Walnut	12	90° W	30				

Survey of Section 32 T. 7 R. 2 E



FIELD NOTES.

Witness Trees	Inches in Diameter	Bearings	Distances in Links	Witness Trees	Inches in Diameter	Bearings	Distances in Links
A	20	$\frac{1}{2}$ distance between N.W. cor & N $\frac{1}{2}$ m.p.					
	20	Woak 12	N 47° W	44 $\frac{1}{2}$			
B		Woak 12	N 86° E	64 $\frac{1}{2}$			
		N $\frac{1}{2}$ m.p. perpetuated					
C	21	Roak 12	N 22° W	11			
	21	Woak 2	S 66 $\frac{1}{2}$ ° W	17			
D		$\frac{1}{2}$ distance bet. N $\frac{1}{2}$ m.p. & center					
	22	B Walnut 4	S 31 $\frac{1}{2}$ ° W	8			
E	23	B Walnut 3	N 63 $\frac{1}{2}$ ° W	28			
		36 rods east of the N.W. corner					
F	24	B Walnut 24	S 86 $\frac{1}{2}$ ° E	178			
		4 rods S of a point 36 rods E of the N.W. cor.					
G	25	Cycamore 24	N. 77 $\frac{1}{2}$ ° E	79 $\frac{1}{4}$			
		16 rods southeastly from a point 4 rods S of a point 36 rods east of the N.W. corner					
H	26	Cycamore 6	S 22° W	28			
	26	elm 2	N 1° W	27			